



Picture Book ReNEW Repairs

© 2020 Bushman Equipment, Inc. This presentation contains information that is **PROPRIETARY** and **CONFIDENTIAL** and must not be duplicated, used, or disclosed without the written consent of Bushman Equipment, Inc.


***Bushman ReNEW™* Examples**



**P&H bottom block in
for refurbishment**

Before

***Bushman ReNEW™* Examples**



**P&H bottom block in
for refurbishment**

Before

Bushman ReNEW™ Examples



P&H bottom block in
for refurbishment

After

***Bushman ReNEW™* Examples**



**P&H bottom block
with new Xtek sheaves**

After

***Bushman ReNEW™* Examples**



**Bushman
Rotating
bottom block**

Before

***Bushman ReNEW™* Examples**



**Bushman
Rotating
bottom block**

Frame acid dipped

Bushman ReNEW™ Examples



**Bushman
Rotating
bottom block**

After

***Bushman ReNEW™* Examples**



**Non-Bushman
C-hook**

Before

Bushman ReNEW™ Examples



**Non-Bushman
C-hook**

After

***Bushman ReNEW™* Examples**



**Bushman Model
900 Pallet Lifter**

Before

Bushman ReNEW™ Examples



**Bushman Model
900 Pallet Lifter**

After

Bushman ReNEW™ Examples



**Bushman Bar
Rack Grab**

Before

***Bushman ReNEW™* Examples**



**Bushman Bar
Rack Grab**

After

***Bushman ReNEW™* Examples**



CMCI Lifting Tong

Before

Bushman ReNEW™ Examples



CMCI Lifting Tong

After

Bushman ReNEW™ Examples



Bushman Model
6107 Double Rim
Vertical Coil Tong

Before

***Bushman ReNEW™* Examples**



**Bushman Model
6107 Double Rim
Vertical Coil Tong**



Stripped

***Bushman ReNEW™* Examples**



**Bushman Model
6107 Double Rim
Vertical Coil Tong**

After



Sheet lifter “Before”



“After”

Bushman *ReNEW* lifter repair

Bushman ReNEW™ Examples



**Bushman Model
M5600 Sheet Lifter**

Before

***Bushman ReNEW™* Examples**



**Bushman Model
M5600 Sheet Lifter**

After

Bushman ReNEW™ Examples



Bushman Model
M5600 Sheet Lifter

After adding a motor

***Bushman ReNEW™* Examples**



Added new motor



Added radio control

**Bushman Model
M5600 Sheet Lifter**



Coil Grab "Before"



"After"

Bushman *ReNEW* lifter repair

***Bushman ReNEW™* Examples**



**Bushman Model
MR5067 Rotating
Coil Grab**

Before

Bushman ReNEW™ Examples



Frame after pickling

**Bushman Model
MR5067 Rotating
Coil Grab**

***Bushman ReNEW™* Examples**



**Bushman Model
MR5067 Rotating
Coil Grab**

After

Bushman ReNEW™ Examples



Bushman Model
M5067 Coil Grab

Before

***Bushman ReNEW™* Examples**



**Bushman Model
MR5067 Rotating
Coil Grab**

**After adding
a new rotator**

***Bushman ReNEW™* Examples**



**Bushman Model
M5067 Coil Grab**

Before

Bushman ReNEW™ Examples



**Bushman Model
M5067 Coil Grab**

After

Bushman ReNEW™ Examples



Bushman Model
M5067 Coil Grab

Before

***Bushman ReNEW™* Examples**



**Bushman Model
M5067 Rotating
Coil Grab**

After

***Bushman ReNEW™* Examples**



**Non-Bushman
telescopic
magnet beam**

Before

Bushman ReNEW™ Examples



Non-Bushman
telescopic
magnet beam

After

Bushman ReNEW™ Examples



Bushman
telescopic
magnet beam

Before

Bushman ReNEW™ Examples



**Bushman
telescopic
magnet beam**

After

Bushman ReNEW™ Examples



Non-Bushman
rotating paper
roll beam

Before

***Bushman ReNEW™* Examples**



**Non-Bushman
rotating paper
roll beam**

Before

***Bushman ReNEW™* Examples**



**Non-Bushman
rotating paper
roll beam**

After

***Bushman ReNEW™* Examples**



**Bushman
rotating paper
roll beam**


Before

Bushman ReNEW™ Examples



Bushman
rotating paper
roll beam

After



Bushman ReNEW™ Examples



Bushman
electrode lifter

Before

***Bushman ReNEW™* Examples**



**Bushman
electrode lifter**

After

Bushman ReNEW™ Examples



**Bushman Flip-
Rite® Modules**

Before

Bushman ReNEW™ Examples



**Bushman Flip-
Rite® Modules**

After